

- 111,5 80. 10
- 2, GR /0-11-6000/171-2/1-3-5-1/9L/6-11-60000/158-7-6-5-1
- D-19/8/68 DEGREES/EH-6A 3.
- 40 1.98
- GOOD/GOOD/GOOD 5.
- TAKE RECEIVED 28/1420Z IN STEEL BOX. CONDITION GOOD. MASKING TAPE USED BY TO SECURE TAKE CAUSED SOME TROUBLE IN RESPOOLING FOR PROCESSING. ADHESIVE BECAME SOFT AND STUCK TO FILM REQUIRING CLEANING. TEAR 9L 1405 AND 1406 CAUSED BY INFERIOR TAPE AND MOISTURE FROM SPLICE. DATA CHAMBER OVER-EXPOSED. FILM CUT ON EH-6A CAUSED LOSS OF TENSION, BACKLASH AND FOGGING OF ABOUT 4 FEET OF FILM. 9R 083 TO 085. BACKLASH ALSO REASON FOR FINGER AND ROLLER MARKS OR Ø63 TO Ø83. TAKE NOT REPEAT NOT REWASHED PRIOR TO SHIPMENT.

25X1A

25X1A

25X1A

INSTALLATION OF NEW EQUIPMENT DELAYED TO PROCESS PLAN TO START FACILITY MODIFICATION WK OF 29 JULY. REF: 4258 (OUT 23583) GROUP 1 EXCLUDED FROM

AUTOMATIC DOWNGRADING AND DECLASSIFICATION.

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED.

Approved For Release 2000/04/19 : CIA-RDP89B00569R000600040002-3

Approved For Release 2000/04/19 : CIA-RDP89B00569R000600040002-3

SECRET

25X1A

1189 (IN 4412Ø)

PAGE TWO

25X1A 25X1A REQUEST TEST -10 BE FURNISHED

ON OR ABOUT 5 AUG 62.

- 7. NOT ACCOMPLISHED
- 8. PLAN TO TURN OVER TO HQS COURIER ON 31 JULY 62.

END OF MESSAGE

SECRET